

## PROPELLER LOGBOOK

PROPELLER MODEL HC-I391R-IN

PROPELLER S/N NY 439B

LOGBOOK #\_\_\_\_

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

## PROPELLER MAINTENANCE RECORD

Position	PITCH RANGE
Propeller Model <u>HC-I3YIR-IN</u>	High/Feather
Propeller S/N NY 439B	Start Lock
Blade Design N7405CK+2	Low
Blade S/N's No. 1 <u> </u>	Reverse
No. 2 D 6873	Aircraft Manufacturer
No. 3 D 67027	Aircraft Model
No. 4	S/N
No. 5	Registration
No. 6	
Spinner Assembly Part No	

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directive Service Documents, Overhaul, Major or Minor Repair, and Inspec	
	Propo	Mer Mer		
Date:	Prope 4/13/23			<del>-</del>
			g. Number: <u>N8033Q</u>	
Prop M	1odel: <i>HC-I3</i> Y	R-1N	S/N: NY 4398	_
Compli	ed with Hartzell Prop	peller Owne	er's Manual /45.	
Perforn Testing	ned Lubrication of I with NYCO GN30	Prop by M.	Manufacturer during Flight bel on Prop after 1 to 2	
	pperation. ure:	Y		
	<b>^</b>		ertificate Number: AP51627416	
Pipī	<i>er</i> pipi	ER AIRCRA	AFT, INC.	
	,		MAC	
	7	; ЭАНЕ	Muncie Aviation Company  An Employee Owned Company	
	Reg. Marl N530MA			
	Annual inspe     Operational a	ction compl	oleted this date. Ref. Piper MM CH 5-20-00. neck of above items found to be satisfactory.	
	See AD Listing D	ated 5/28/2	2024 for details.  Annual Inspection and was determined	-
	to be in airworthy	condition. ns of Federa pair/inspect	The aircraft/component identified above was repaired and inspected in accordance with rall Aviation Agency, approved for return to service.  Stion are on file atthis: C.R.S under Shop Order No	
	Date: 6/13/2024	l Siane	Inspector for Muncie Aviation Company Indiana 47303 765-289-7141	
+				